

CHAPTER 6

Control Charts for Attributes

Expected Outcomes

Know limitations of variable control charts and the different types of attribute charts.

Know the objectives of the p chart group and the applicable distribution.

Be able to construct a:

Fraction defective chart- fixed subgroup size

Fraction defective chart-variable subgroup size

Percent defective chart

Number defective chart

Attribute

- ❑ The term Attribute refers to those quality characteristics that conform to specifications or do not conform to specifications.

Attribute are used:

- Where measurements are not possible.
- Where measurements can be made but are not made because of time, cost, or need.

Types of Attribute Charts:

1. Nonconforming Units (based on the Binomial distribution): p chart, np chart.
2. Nonconformities (based on the Poisson distribution): c chart, u chart.

The P Chart

- ❑ The P Chart is used for data that consist of the proportion of the number of occurrences of an event to the total number of occurrences.
- ❑ It is used in quality to report the fraction or percent nonconforming in a product, quality characteristic, or group of quality characteristics.

The P Chart

Formula:

$$p = \frac{np}{n}$$

- ❑ The fraction nonconforming, p , is usually small, say, 0.10 or nonconforming is very small, the subgrless.
- ❑ Because the fraction oup sizes must be quite large to produce a meaningful chart.

The P Chart

- ❑ It can be used to control one quality characteristic, as is done with X bar and R chart,
- ❑ Or to control a group of quality characteristics of the same type or of the same part,
- ❑ Or to control the entire product.
- ❑ It can be established to measure the quality produced by a work center, by a department, by a shift, or by an entire plant.

The P Chart

Objectives of the P Chart:

1. Determine the average quality level: This information provides the process capability in terms of attributes.
2. Bring to the attention of management any changes in the average.
3. Improve the product quality: Ideas for quality improvement.

P -Chart Construction for Constant Subgroup Size

1. Select the quality characteristic(s):
 - a) Single quality characteristic.
 - b) Group of quality characteristics.
 - c) A part.
 - d) An entire product.
 - e) A number of products.
 - f) It can be established for performance control of an operator, work center, department, shift, plant, or corporation

The P Chart

P Chart Construction for Constant Subgroup Size
cont'd.

2. Determine the subgroup size and method:
 - ❑ The size of the subgroup is a function of the proportion nonconforming.
 - ❑ A minimum size of 50 is suggested as a starting point.

The P Chart

P Chart Construction for Constant Subgroup Size
cont'd.

3. Collect the data:

- ☐ At least 25 subgroups.
- ☐ Different sources (Check sheet).
- ☐ For each subgroup the proportion nonconforming is calculated by the formula

$$P = np/n$$

The P Chart

P Chart Construction for Constant Subgroup Size


4. Calculate the trial central line and the control limits:

$$\bar{p} = \frac{\sum np}{\sum n}$$

$$UCL = \bar{p} + 3\sqrt{\frac{\bar{p}(1 - \bar{p})}{n}}$$

$$LCL = \bar{p} - 3\sqrt{\frac{\bar{p}(1 - \bar{p})}{n}}$$

p Chart




The P Chart

P Chart Construction for Constant Subgroup Size
cont'd.

5. Establish the revised central line and control limits.


$$\overline{p}_{new} = p_0 = \frac{\sum np - np_d}{\sum n - n_d}$$
$$UCL = p_0 + 3\sqrt{\frac{p_0(1 - p_0)}{n}}$$
$$LCL = p_0 - 3\sqrt{\frac{p_0(1 - p_0)}{n}}$$



The P Chart

P Chart Construction for Variable Subgroup Size

1. Collect the data.
2. Determine the trial central line and control limits: Since the subgroup size changes each day, limits must be calculated for each day.



The P Chart

P Chart Construction for Variable Subgroup Size
cont'd.

2. As the subgroup size gets larger, the control limits are closer together.
3. Establish revised central line and control limits:

The P Chart

P Chart Construction for Variable Subgroup Size cont'd.

- ❑ If P_o is known, the process of data collection and trial control limits is not necessary.
- ❑ P is the proportion (fraction) nonconforming in a single subgroup.
- ❑ P_{bar} is the average proportion (fraction) nonconforming of many subgroups.

The P Chart

P Chart Construction for Variable Subgroup Size
cont'd.

- ❑ P_o is the standard or reference value of the proportion (fraction) nonconforming based on the best estimate of $P\bar{a}$.
- ❑ Φ is the population proportion (fraction) nonconforming.

The P Chart

Minimizing the Effect of Variable Subgroup Size

1. Control limits for an average subgroup size: By using an average subgroup size, one limit can be calculated and placed on the control chart.

$$n_{av} = \frac{\sum n}{g}$$

$$UCL = p_0 + 3\sqrt{\frac{p_0(1 - p_0)}{n_{av}}}$$

$$LCL = p_0 - 3\sqrt{\frac{p_0(1 - p_0)}{n_{av}}}$$




Chart for May Data Illustrating Use of an Average Subgroup Size

The np Chart

Number Nonconforming Chart (np):

- ❑ The np chart is easier for operating personnel to understand than the p chart.
- ❑ The limitation that this chart has is that the subgroup size needs to be constant.

The np Chart


Central Line = np_0

Control Limits = $np_0 \pm 3\sqrt{np_0(1 - p_0)}$

The np Chart

Number Nonconforming Chart (np):

- ❑ If the fraction nonconforming p_0 is unknown, then it must be determined by collecting data, calculating trial control limits, and obtaining the best estimate of p_0 .



Number Nonconforming Chart (np Chart)

Process Capability

- ❑ For an attribute this process is much simpler.
- ❑ The process capability is the central line of the control chart.
- ❑ Management is responsible for the capability.
- ❑ When the plotted point is outside the control limit, operating personnel are usually responsible.

