

BFF1113

Engineering Materials



DR. NOOR MAZNI ISMAIL
FACULTY OF MANUFACTURING ENGINEERING

Course Guidelines:

1. Introduction to Engineering Materials
2. Bonding and Properties
3. Crystal Structures & Properties
4. Imperfection in Solids
5. Mechanical Properties of Materials
6. Physical Properties of Materials
7. Failure & Fundamental of Fracture
8. Metal Alloys
9. Phase Diagram
10. Phase Transformation – Heat Treatment
11. Processing and Application of Metals
12. Ceramic Materials
13. Polymer Materials
14. Composite Materials
15. Corrosion & Degradation of Materials
16. Environment and Sustainability

METAL

1. INTRODUCTION TO METALS & ALLOYS : GENERAL PROPERTIES & APPLICATIONS
- 2. PHASE DIAGRAM**
3. FABRICATION & THERMAL PROCESSES OF METALS



PHASE DIAGRAM

Introduction

- Phase diagram provides valuable information about melting, crystallization, etc.
- It shows the relationships among temperature, composition, and phases present in a particular alloy system at equilibrium.
- Binary alloy- consist 2 components (e.g. Cu-Ni, Cu-Ag, Pb-Sn)
- Ternary alloy- consist of 3 components (e.g. Fe-Ni-Cr)

• **Why study phase diagram?**

Important to engineers, related to design and control of heat-treating procedures since there is a strong correlation between microstructure and mechanical properties

Phase Equilibria: Solubility Limit

- **Solubility Limit:**

Max concentration for which only a single phase solution occurs.

Question: What is the solubility limit at 20°C?


Answer: 65 wt% sugar.

If $C_0 < 65$ wt% sugar: syrup

If $C_0 > 65$ wt% sugar: syrup + sugar.

The solubility limit of sugar in water depends on the temperature of water
e.g., if $T = 100^\circ\text{C}$, solubility limit = 80 wt% sugar.


Sucrose/Water Phase Diagram



Effect of T & Composition (C_o)

- Changing T can change # of phases: path A to B .
- Changing C_o can change # of phases: path B to D .

water- sugar
system




Adapted from
Fig. 9.1,
Callister 7e.


Binary System

Alloy that contain 2 components

(1) Isomorphous – complete liquid and solid solubility of the 2 components, e.g. Cu-Ni




(2) Eutectic – limited solubility, upon cooling liquid phase is transformed into 2 solid phases. e.g. Cu-Ag, Pb-Sn



Binary Isomorphous Phase Diagrams

- binary systems: just 2 components.
- independent variables: T and C_0 ($P = 1$ atm is almost always used).

• Phase Diagram for Cu-Ni system



- 2 phases:
 - L (liquid)
 - α (FCC solid solution)


- 3 phase fields:
 - L
 - $L + \alpha$
 - α

Noted: Solidus line & Liquidus line

Binary Isomorphous

At temperature below 1080°C, Cu & Ni are soluble in each other (complete solubility) due to;

- i. Same crystal structure (FCC)
- ii. Nearly identical atomic radii
- iii. Nearly identical electronegativity
- iv. Similar valences





Interpretation of Phase Diagrams

- 3 kind of information are available:
 - i. Type of phase that are present
(*α phase or L phase or $\alpha + L$ phase?*)
 - ii. The composition of these phases
% of composition **e.g.: Cu or Ni**
 - iii. The percentage or weight fractions of the phases **e.g.: % L or % α**


TERMS THAT YOU NEED TO KNOW...

- The *lowest* temperature at which the alloy is still completely liquid is known as the **Eutectic point**
- The lowest temperature at which a single solid phase (austenite) transforms into two other solid phase (ex. ferrite and cementite) is known as the **Eutectoid point**
- **Ferrite**
- **Austenite**
- **Cementite**
- **Pearlite**
- **Spherodite**
- **Bainite**
- **Martensite**
- **Retained Austenite**
- **Tempered Martensite**




Ferrite

- **Alpha ferrite** denoted α -ferrite or **ferrite**
- Delta ferrite (δ -ferrite) is stable only at very high temperatures
- Ferrite is soft and ductile
- It is magnetic from room temperature to 768°C , *Curie temperature*



Austenite

- Within a certain temperature range, iron undergoes a **polymorphic transformation** from a bcc to a fcc structure,
- Becomes *gamma iron* (γ -iron) or **austenite**
- Austenite is denser than ferrite and important in heat treatment
- Possesses good formability





Cementite

- Also called **carbide**
- Cementite is very hard and brittle intermetallic compound
- Has a significant influence on the properties of steels




Pearlite

- **Fine pearlite** is where **ferrite and cementite lamellae** in the pearlite structure of the eutectoid steel are thin and closely packed
- **Coarse pearlite** is thick and widely spaced



Spheroidite

- **Subcritical annealing** is when pearlite is heated to just below the eutectoid temperature for a period of time
- **Spheroidites** are less conducive to stress concentration because of their rounded shapes





Bainite

- **Bainite** is a acicular microstructure, a very fine microstructure consisting of **ferrite and cementite** having a different morphology
- Produced in steels with alloying elements and at cooling rates that are higher than those required for transformation to pearlite



Martensite

- As austenite is cooled at a high rate, fcc structure is transformed into a **body-centered** structure
- Does not have as many slip systems, thus lacks toughness and limited use




Retained Austenite

- When alloy temperature is not quenched sufficiently low, only a portion of the structure is transformed to martensite.
- The rest is **retained austenite** which can cause dimensional instability and cracking.
- Lower the hardness and strength of the alloy.

Tempered Martensite

- **Tempering** is a heating process to reduce hardness and improve toughness, thus improve the mechanical properties of the metal.
- With increasing tempering time and temperature, the hardness of tempered martensite decreases.



1

i. Type of Phase that are present

- **Rule 1:** If we know T and C_0 , then we know:
--the # and types of phases present.


- **Examples:**

A(1100°C, 60):

1 phase = α

B(1250°C, 35):

2 phases = $L + \alpha$



Phases: The physically and chemically distinct material regions, e.g., α and β in Aluminum-Copper alloy

Composition of phases


2

- Rule 2: If we know T and C_o , then we know: the composition of each phase.

There are 2 cases:

- a. Single phase region
- b. Two phase region

Components: The elements or compounds which are present in the mixture (e.g. Al and Cu)




a. Single phase region


- The phase compositions are easy to be determined

- e.g.: Point A
(60 wt% Ni-40 wt% Cu at 1100°C)

At this C_o and T

- Only α phase is present
- Composition = 60 wt% Ni-40 wt% Cu





b. Two phase region

- The phase composition can be determined by **tie line**.

- Examples:

$$C_0 = 35 \text{ wt\% Ni}$$

At $T_A = 1320^\circ\text{C}$:

Only Liquid (L)

$$C_L = C_0 (= 35 \text{ wt\% Ni})$$

At $T_D = 1190^\circ\text{C}$:

Only Solid (α)


$$C_\alpha = C_0 (= 35 \text{ wt\% Ni})$$

At $T_B = 1250^\circ\text{C}$:

Both α and L

$$C_L = C_{\text{liquidus}} (= 32 \text{ wt\% Ni here})$$

$$C_\alpha = C_{\text{solidus}} (= 43 \text{ wt\% Ni here})$$



3

iii. Weight fraction of phase

- Rule 3: If we know T and C_0 , then we know:
--the amount of each phase (given in wt%).

- There are 2 cases:

→ a) Single phase region

→ b) Two phase region


a) Single phase region

■ Example: Point A
(60 wt% Ni-40 wt% Cu at
1100°C)


At this C_0 and T ;

- Only α phase is present
- The alloy is composed entirely of this phase, so the phase fraction;


$$W_{\alpha} = \underline{1.0 \text{ (or 100\%)}}$$



b) Two phase region



Tie line and Lever Rule
(inverse lever Rule) must be
utilized C_0



$$W_L = \frac{C_{\alpha} - C_0}{C_{\alpha} - C_L} = \frac{S}{R + S}$$

$$W_{\alpha} = \frac{C_0 - C_L}{C_{\alpha} - C_L} = \frac{R}{R + S}$$

- total weight fraction: $W_L + W_{\alpha} = 1$

b) Two phase region (continue...)

- Examples:

$C_0 = 35 \text{ wt\% Ni}$

At T_A : Only Liquid (L)

$W_L = 100 \text{ wt\%}, W_\alpha = 0$


At T_D : Only Solid (α)

$W_L = 0, W_\alpha = 100 \text{ wt\%}$

At T_B : Both α and L


$$W_L = \frac{C_\alpha - C_0}{C_\alpha - C_L} = \frac{43 - 35}{43 - 32} = 73 \text{ wt\%}$$

$$W_\alpha = \frac{C_0 - C_L}{C_\alpha - C_L} = 27 \text{ wt\%}$$




The Lever Rule

- Tie line – connects the phases in equilibrium with each other



How much of each phase?

Think of it as a lever (teeter-totter)



$$W_L = \frac{M_L}{M_L + M_{\alpha}} = \frac{S}{R + S} = \frac{C_{\alpha} - C_0}{C_{\alpha} - C_L}$$

$$W_{\alpha} = \frac{R}{R + S} = \frac{C_0 - C_L}{C_{\alpha} - C_L}$$

Development of Microstructure

a. **Equilibrium cooling**

extremely slow cooling. Readjustment in the L and α phases composition in accordance with the phase diagram

b. **Nonequilibrium cooling**

cooling rate too rapid to allow these compositional readjustment, thus nonequilibrium microstructure develop

a. Equilibrium cooling

i. Point a (1300°C)

Alloy is in liquid form

ii. Point b (1260°C)

α phase begin to form at liquidus line,
based on tie line, the composition is;

L = 35wt% Ni-65wt% Cu

α = 46wt% Ni-54wt% Cu

iii. Point c (1250°C)

solid α & liquid composition

L = 32wt% Ni-68wt% Cu

α = 43wt% Ni-57wt% Cu


iv. Point d (1220°C)

Solidification is virtually completed

v. Point e (1180°C)

Solidification complete, Final product-
polycrystalline α phase solid solution

α = 35 wt % Ni- 65 wt% Cu




b. Nonequilibrium cooling

Nonequilibrium cooling :

Point c (1250°C)
grain boundary

Point d (1220°C)
Solidification should be
completed, however there is
still liquid remaining


Point e (1180°C)
Solidification reaches
completion



Nonequilibrium vs. Equilibrium Cooling

In nonequilibrium system

- **Cu-Ni system:** First α to solidify has $C_{\alpha} = 46\text{wt\%Ni}$.
Last α to solidify has $C_{\alpha} = 35\text{wt\%Ni}$.



Nonequilibrium cooling


Rapid cooling rate. Segregation or concentration gradients are established

Equilibrium cooling


Slow rate, composition in accordance with the phase diagram

Mechanical Properties

- Effect of composition on mechanical properties (Tensile strength and elongation) of Copper-nickel system:




--At some intermediate composition, the curve passes through the maximum




--The ductility decreases with the addition of second component, where the curve exhibit the minimum

Binary Eutectic System



- Eutectic transition



- The solubility of solid phases (α and β) is limited, e.g. solubility limit α phase is at CBA boundary line.
- Example copper-silver phase diagram
- 3 single-phase region exist
 - α phase (rich in copper)
 - β phase- (rich in silver)
 - liquid

EX: Pb-Sn Eutectic System (1)

- For a 40 wt% Sn-60 wt% Pb alloy at 150°C, find...
 - the phases present: $\alpha + \beta$
 - compositions of phases:

$$C_o = 40 \text{ wt\% Sn}$$

$$C_\alpha = 11 \text{ wt\% Sn}$$

$$C_\beta = 99 \text{ wt\% Sn}$$


- the relative amount of each phase:

$$W_\alpha = \frac{S}{R+S} = \frac{C_\beta - C_o}{C_\beta - C_\alpha}$$

$$= \frac{99 - 40}{99 - 11} = \frac{59}{88} = 67 \text{ wt\%}$$

$$W_\beta = \frac{R}{R+S} = \frac{C_o - C_\alpha}{C_\beta - C_\alpha}$$

$$= \frac{40 - 11}{99 - 11} = \frac{29}{88} = 33 \text{ wt\%}$$



EX: Pb-Sn Eutectic System (2)

- For a 40 wt% Sn-60 wt% Pb alloy at 200°C, find...

--the phases present: $\alpha + L$

--compositions of phases:

$$C_o = 40 \text{ wt\% Sn}$$

$$C_\alpha = 17 \text{ wt\% Sn}$$


$$C_L = 46 \text{ wt\% Sn}$$

--the relative amount of each phase:

$$W_\alpha = \frac{C_L - C_o}{C_L - C_\alpha} = \frac{46 - 40}{46 - 17}$$


$$= \frac{6}{29} = 21 \text{ wt\%}$$

$$W_L = \frac{C_o - C_\alpha}{C_L - C_\alpha} = \frac{23}{29} = 79 \text{ wt\%}$$



Microstructures in Eutectic Systems: I


- $C_0 < 2 \text{ wt\% Sn}$
- **Result:**
 - at extreme ends
 - polycrystal of α grains
i.e., only one solid phase.



Microstructures in Eutectic Systems: II


- $2 \text{ wt\% Sn} < C_0 < 18.3 \text{ wt\% Sn}$
- **Result:**

- Initially liquid + α
- then α alone
- finally two phases
 - α polycrystal
 - fine β -phase inclusions




Microstructures in Eutectic Systems: III

- $C_0 = C_E$
- **Result:** Eutectic microstructure (lamellar structure)
--alternating layers (lamellae) of α and β crystals.





Micrograph of Pb-Sn
eutectic
microstructure




160 μm

Adapted from Fig. 9.14, Callister 7e.

 Eutectic reaction; $L \rightleftharpoons \alpha + \beta$ (Refer to copper-silver phase diagram at 71.9 wt% Ag)

 Eutectoid reaction – 1 solid phase \rightarrow 2 other solid phases (upon cooling)




 Peritectic reaction – 1 solid phase + 1 liquid phase \rightarrow 1 ^{another} _{solid} phase (upon cooling)



THE IRON – IRON CARBON (Fe – Fe₃C)

- In practice, all steel and cast iron have carbon content less than 6.7 wt % C, thus we consider only this phase diagram- iron-iron carbide system
- Carbon is an interstitial impurity in iron.




Iron-Carbon (Fe-C) Phase Diagram

- 2 important points

-Eutectic (A):
 $L \Rightarrow \gamma + \text{Fe}_3\text{C}$


-Eutectoid (B):
 $\gamma \Rightarrow \alpha + \text{Fe}_3\text{C}$



120 μm

Result: Pearlite =
alternating layers of
 α and Fe_3C phases


(Adapted from Fig. 9.27, Callister 7e.)



Adapted from Fig. 9.24, Callister 7e.

Hypoeutectoid Steel

Co less than
Eutectoid;
0.002 -
0.76 wt% C



$$w_\alpha = \frac{s}{r+s}$$


$$w_\gamma = (1 - w_\alpha)$$

$$w_\alpha = \frac{S}{R+S}$$

$$w_{\text{Fe}_3\text{C}} = (1 - w_\alpha)$$



pearlite
 $w_{\text{pearlite}} = w_\gamma$




pearlite

proeutectoid ferrite

100 μm Hypoeutectoid steel

Adapted from Fig. 9.30, Callister 7e.

Fraction of Pearlite & Proeutectoid α



$$\text{Fraction of Pearlite, } W_p = \frac{T}{T+U}$$

$$\text{Fraction of Proeutectoid } \alpha, W_a = \frac{U}{T+U}$$

- Ferrite that is present in the pearlite is called eutectoid ferrite
- In terms of % C, terms like hypo and hyper-eutectoid alloys are used
- In term of T, Ferrite that formed before eutectoid T is called as proeutectoid ferrite

Example: Phase Equilibria

For a 99.6 wt% Fe-0.40 wt% C at a temperature just below the eutectoid, determine the following

- a) composition of Fe_3C and ferrite (α)**
- b) the amount of carbide (cementite) in grams that forms per 100 g of steel**
- c) the amount of pearlite and proeutectoid ferrite (α)**


Solution:

a) composition of Fe₃C and ferrite (α)

$$C_0 = 0.40 \text{ wt\% C}$$

$$C_{\alpha} = 0.022 \text{ wt\% C}$$

$$C_{\text{Fe}_3\text{C}} = 6.70 \text{ wt\% C}$$



Solution:

b) the amount of carbide (cementite) in grams that forms per 100 g of steel

$$\frac{\text{Fe}_3\text{C}}{\text{Fe}_3\text{C} + \alpha} = \frac{C_0 - C_\alpha}{C_{\text{Fe}_3\text{C}} - C_\alpha} \times 100$$

$$= \frac{0.4 - 0.022}{6.7 - 0.022} \times 100 = 5.7 \text{ g}$$

$$\text{Fe}_3\text{C} = 5.7 \text{ g}$$

$$\alpha = 94.3 \text{ g}$$

Solution:

c) the amount of pearlite and proeutectoid ferrite (α)
note: amount of pearlite = amount of γ just above T_E

$$C_o = 0.40 \text{ wt\% C}$$

$$C_\alpha = 0.022 \text{ wt\% C}$$

$$C_{\text{pearlite}} = C_\gamma = 0.76 \text{ wt\% C}$$

$$\frac{\gamma}{\gamma + \alpha} = \frac{C_o - C_\alpha}{C_\gamma - C_\alpha} \times 100 = 51.2 \text{ g}$$

$$\text{pearlite} = 51.2 \text{ g}$$

$$\text{proeutectoid } \alpha = 48.8 \text{ g}$$

