COMPUTER AIDED ENGINEERING DESIGN (BFF2612)

LAB. EXERCISE 1

by
Dr. Mohd Nizar Mhd Razali
Faculty of Manufacturing Engineering
mnizar@ump.edu.my

Universiti
Malaysia
PAHANG
Engineering • Technology • Creativity

LAB. EXERCISE 1

Computer Aided Engineering
Design: Dr Nizar

STEP 1

Draw the sketch of the base feature on the YZ plane, as shown in Figure below.

Unit is in mm

Computer Aided Engineering
Design: Dr Nizar

STEP 2

Extrude the sketch to two directions (75 mm each) as shown in Figure below.

Computer Aided Engineering
Design: Dr Nizar

STEP 3

- **Create the second feature, which is a Pocket feature, as shown in both Figures below.**
- **Use tangency between line and arcs when using mirror.**

R=75 mm

Computer Aided Engineering
Design: Dr Nizar

STEP 4

- **Create the third feature by extruding a sketch, drawn on a plane at an offset from the XY plane (41.27 mm), as shown in Figures.**
- **Use pad with height of 125 mm to top and use up to next to bottom direction.**

Surface to be selected

D 150

150

Section B–B

Computer Aided Engineering
Design: Dr Nizar

STEP 5

Create the fourth feature which is a Groove feature, as shown in the following Figures.

Computer Aided Engineering
Design: Dr Nizar

STEP 6

Create the last feature of the model which is the Pocket feature, as shown in the following Figures.

Computer Aided Engineering
Design: Dr Nizar

COMPUTER AIDED ENGINEERING DESIGN (BFF2612)

Dr. Nizar

Communitising Technology