COMPUTER AIDED ENGINEERING DESIGN (BFF2612)

ASSIGNMENT 2

by
Dr. Mohd Nizar Mhd Razali
Faculty of Manufacturing Engineering
mnizar@ump.edu.my

COMPUTER AIDED ENGINEERING DESIGN BFF2612

SELF PRACTICES
SKETCHER WORKBENCH

Computer Aided Engineering
Design: Dr Nizar

INSTRUCTIONS

Select appropriate plane and draw the sketch of the model shown in **Figure A**. The sketch dimension is shown in **Figure B**. If dimensions are not shown, simply sketch in the sketcher so that the model looks similar to the figure given. Your sketch must be fully defined.

Model 1

Figure A

Figure B

Model 2

Figure A

Figure B

Model 3

Figure A

**Figure B**

Model 4


Figure A

Figure B

COMPUTER AIDED ENGINEERING DESIGN (BFF2612)

Dr. Nizar

Communitising Technology