

Process Monitoring

by Mohd Yusri Mohd Yunus yusri@ump.edu.my



Process Monitoring



Chapter 2 Statistical Process Control



Process Monitoring

Chapter Description

- Aims
 - Analyze process performance using the SPC methodology.
- Expected Outcomes
 - Apply as well as analyze the univariate monitoring performance based on the progression of the means and range charts of SPC framework.
- Other related Information



Subtopics


2.3 Process Shifting

2.4 Patterns



Process Monitoring


2.3 Process Shifting



Sampling mean is shifting upward but range is consistent




2.3 Process Shifting



Sampling mean is constant but dispersion is increasing








Normal behavior. Process is "in control."








One plot out of above (or below) the 99% limit. Investigate for root cause. Process is not necessary "out of control."








Trends in either direction for at least 5 plots successively. Investigate for the root cause.







Run of 5 above (or below) of the central line. Investigate for the root cause.



References

- <u>http://www.statit.com/statitcustomqc/StatitCustomQ</u>
 <u>C_Overview.pdf</u>
- <u>https://www.aidt.edu/course_documents/Manufacturi</u> ng_Skills/SPC/Intro_to_SPC.pdf





Authors Information

Credit to the authors:



Process Monitoring