

PROCESS INTEGRATION Part 1: Heat Integration

Quiz Chapter 2



- What will happen if the ∆Tmin is reduced to half?
- What will happen if the ∆Tmin is increased to half?